



林野庁
近畿中国森林管理局
滋賀森林管理署

Figure 1 consists of four photographs arranged in a 2x2 grid, illustrating the construction of a stepped slope. The top-left photo shows a steep, eroded slope with exposed tree roots. The top-right photo shows a slope with vertical wooden posts and horizontal logs. The bottom-left photo shows a slope covered in green geotextile fabric with vertical posts. The bottom-right photo shows a slope with horizontal concrete steps and vertical posts.



平成25年 台風18号の影響に伴う山地災害からの復旧状況について (参考資料)

林 野 庁
近畿中国森林管理局
滋賀森林管理署



年度別事業実施状況一覧表				
年度	市町	国有林	工種	数量
H26	近江八幡市	奥島山	谷止工	2基
			山腹工	1箇所(0.25ha)
	野洲市	三上山	山腹工	3箇所(0.22ha)
	大津市	大谷	山腹工	1箇所(0.09ha)
		関寺	谷止工	3基
			山腹工	1箇所(0.02ha)
		木ノ下谷	谷止工	1基
		追分	谷止工	1基
			流路工	96.5m
		山腹工	3箇所(0.23ha)	
		六個山	谷止工	2基
貝掛	谷止工	1基		
H27	近江八幡市	奥島山	谷止工	1基
			山腹工	3箇所(0.39ha)
	大津市	関寺	谷止工	1基
			山腹工	1箇所(0.04ha)
		大谷	山腹工	1箇所(0.03ha)
H28	野洲市	三上山	山腹工	1箇所(0.02ha)
	大津市	馬ヶ瀬山	山腹工	1箇所(0.09ha)
H29	大津市	一丈野	谷止工	2基
		追分	山腹工	1箇所(0.10ha)
H30	近江八幡市	奥島山	山腹工	1箇所(0.23ha)
	竜王町	竜王山	谷止工	1基
			山腹工	1箇所(0.14ha)
	大津市	追分	山腹工	1箇所(0.10ha)
		貝掛	谷止工	1基
H26～H30 (計)			谷止工	16基
			流路工	96.5m
			山腹工	20箇所(1.95ha)