

R5.7豪雨仁別林道災害 6 号箇所①

林道幅員

※森林博物館から約0.6km地点



R5.7豪雨仁別林道災害 6 号箇所②

林道幅員



R5.7豪雨仁別林道災害 7 号箇所①

林道幅員

※森林博物館から約0.9km地点



R5.7豪雨仁別林道災害 7 号箇所②



林道幅員

R5.7豪雨仁別林道災害 8 - 1 号箇所①

林道幅員

※森林博物館から約1.8km地点



R5.7豪雨仁別林道災害 8 - 1 号箇所②



An aerial photograph showing a forest road that has been completely blocked by a large pile of debris, including logs, branches, and rocks. The road is marked with two parallel red lines. The surrounding area is a dense forest of green trees. The debris pile is located in the center of the image, and the road extends from the bottom left towards the top right.

R5.7豪雨仁別林道災害 8 - 2 号箇所①

林道幅員

※森林博物館から約1.9km地点

R5.7豪雨仁別林道災害 8 - 2 号箇所②

林道幅員



R5.7豪雨仁別林道災害 9 号箇所①

林道幅員

※森林博物館から約2.4km地点



R5.7豪雨仁別林道災害 9 号箇所②

林道幅員



R5.7豪雨仁別林道災害10号箇所①

林道幅員

※森林博物館から約2.6km地点



R5.7豪雨仁別林道災害10号箇所②

林道幅員



R5.7豪雨仁別林道災害11号箇所①

林道幅員

※森林博物館から約2.9km地点



R5.7豪雨仁別林道災害11号箇所②

林道幅員



R5.7豪雨仁別林道災害11号箇所③

林道幅員



仁別林道終点被災状況

